




## BIOS flash with ME

- Copy BIOS files into DOS bootable USB flash drive.
- Boot up and press 'DEL' Key to BIOS screen
- BIOS → PCH-FW Configuration → Firmware Update configuration → Me FW Image Re-flash → Change to Enabled and save.
- Boot from USB flash drive contain BIOS files.
- At DOS prompt; type update.bat and Enter





Flash completed.

```
C:\>afudos hd630b47.16h /p /b /n /x /me
+-----+
|               AMI Firmware Update Utility(APTIO)  v2.39               |
|               Copyright (C)2011 American Megatrends Inc. All Rights R   |
+-----+
Reading file ..... done
- ME Data Size checking . ok
FFS checksums ..... ok
Erasing flash ..... done
Writing flash ..... done
Verifying flash ..... done
Erasing NVRAM ..... done
Writing NVRAM ..... done
Verifying NVRAM ..... done
Erasing BootBlock ..... done
Writing BootBlock ..... done
Verifying BootBlock ... done
Input the ME data into the BIOS ..... done
- Update success for /FDI!!
No PDR regions found in System ME Firmware.
- Update success for /GBE!!
- Update success for /MER!!
- WARNING : System must power-off to have the changes take effect
C:\>
```

